Service Bulletin #2344

May 17, 2012

IOL Service Pack

The information in this Service Bulletin applies to:

- IOL
- Passport Software
- Training

Summary

The following Service Pack has been released for IOL locations, which is Version 8.05.30.01H. This is for IOL sites currently running V8.05.30.01 software.

Details

If you are installing an IOL location with Version 8.05.30.01 software, you need to ensure it is installed with at least the G service pack. The part number for the IOL Version 8.05.30.01H service pack is KS730-002HSP.

This notice does not serve as authorization to perform a site visit to upgrade an existing site. It is intended to notify you of the H service pack release for purposes of upgrading V8.05.30.01 IOL locations that have not yet been installed.

NOTE: Confirm the installation of this service pack on the Server and all Clients at the site at time of equipment installation.

More Information

All IOL sites that are currently running V8.05.30.01 are being remotely upgraded to the H service pack by the IOL Call Center.