

M07555A004 Power Supply Change

Related Equipment:

- Encore 500
- Encore S
- Encore 700 S
- All Encore models retrofit with a DIN rail power supply

Recently a change was made on the M07555A004 power supply assembly, affecting the M07121A004 power supply board. Previous revisions of this board (M07121A002, M07121A001) utilized soldered solid state relays. To enhance serviceability of the power supply board, the soldered solid state relays have now been changed to a socketed relay. The new socketed relay's part number is Q11767-01.

If you suspect that the relay on the board is not functioning properly, you now have the option of troubleshooting the issue by moving the relay from an unused position to test. All boards come with 4 positions populated; relays used will depend upon unit configuration.

It is recommended that you do not plug in the STP wiring connector until the issue you are troubleshooting is resolved. This will assist you in isolating and resolving potential field wiring issues.

M07121A001 or M07121A002 with soldered relays:



M07121A004 with socketed relays:

