



January-30-13 4:48 PM

**Attn: NEE Service Managers and DSS Subcontractors**

**Subject: E500 Hose Pressurization**

This is a reminder to all technicians that when commissioning E500 dispensers that **Command Code 55 (Hose Pressurization) must be TURNED ON**. Leaving it at the default will set the option to OFF. When Command Code 55 is turned on please note:

Option 1 = 10 minutes of idle time

**Option 2 = 30 minutes of idle time (THE PREFERRED CHOICE)**

Using **option 2** will help alleviate the 5 to 7 cent count-up BEFORE fuel is dispensed. Owing to cold weather, fuel price/ fuel shrinkage this 5 to 7 cent count-up may increase customer cost and affect end-user confidence.

**Please also note, Command Code 49 (STP Prestart) should be set at Option 2 = ON.**

These two Command Codes should be set at all Canadian sites.

Thanks,

Mohammed Hafiz

Gilbarco Veeder-Root | Field Engineer | Central & Eastern Canada | Phone 289-997-6808 | Cell 647-210-9126