



April-05-13 4:26 PM

Attn: NEE Service Managers and DSS Subcontractors

This is a reminder that the following GVR service bulletins have been released and have been posted on the NEE FTP site. Please ensure you and your technicians have read them:

- Service Bulletin 2421 – New SPOT Update FlexPay Maintenance Tool 1
- Service Bulletin 2423 – TCR Card Reader Conversion to a HCR Card Reader 4
- Service Bulletin 2430 – Jumper Settings for M06194 PPU Board
- Service Bulletin 2432 – Gasket Paper Removal
- Service Bulletin 2436 – HCR 2 Technical Training Module on LMS
- Service Bulletin 2437 – IOL K Service Pack Release
- Service Bulletin 2438 – Removing Debris Blockages From the Panasonic Dual Head Card Reader

Also, the following **Passport patch** has been added to Patches in the Passport and Software folder on the FTP site: **8.05.XX.01K**

Best regards,
Valorie

Valorie Hennessey BA BEd
Corporate Trainer/ERP Specialist
National Energy Equipment Inc
1850 Derry Rd East
Mississauga ON L5S 1Y6
B: (905) 564 - 2422 x1310
B: (905) 766 -1310
C: (647) 654-8185
vhennessey@nee.ca