



September-11-13 11:35 AM

**Subject:** GVR Service Bulletins Posted on FTP Site  
**Importance:** High

**Attn: NEE Service Managers and DSS Subcontractors**

This is a reminder that the following GVR service bulletins have been released and have been posted on the NEE FTP site. Please ensure you and your technicians have read them:

- Service Bulletin 2467 – MDE-5112 EMV Spot Canada Activation Switch Kit Installation Instructions
- Service Bulletin 2471 – One Touch Canada Service Launch Bulletin
- Service Bulletin 2473 – M07555A004 Assembly Relay Change Rev. 1

Best regards,  
Valorie

**Valorie Hennessey BA BEd**  
*Corporate Trainer/ERP Specialist*  
*National Energy Equipment Inc*  
*1850 Derry Rd East*  
*Mississauga ON L5S 1Y6*  
*B: (905) 564 - 2422 x1310*  
*B: (905) 766 -1310*  
*C: (647) 654-8185*  
[vhennessey@nee.ca](mailto:vhennessey@nee.ca)